UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

: 7,493,288 B2

Page 1 of 1

APPLICATION NO.: 10/711965

DATED

: February 17, 2009

INVENTOR(S)

: Bishop et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the Title Page, Item (75) Inventors

The first named inventor listed on the face of the patent in two places as "Biship" should be changed to --Bishop--.

Column 1, line 6, "invention ('965 application)" should be changed to --application--; line 8, "The '965" should be changed to --This--; line 8, "continuation" should be changed to --continuation in part--.

Claim 16, column 30, line 1, "RE" should be changed to --RF--.

Claim 18, column 30, line 24, "RE" should be changed to --RF--.

Signed and Sealed this

Sixteenth Day of June, 2009

JOHN DOLL Acting Director of the United States Patent and Trademark Office